## Approved For Release 2004/02/13: CIA-RDP80-00810A001300270005-3

2EV4A

	CLASSICICATION	#\J z	
-		TION REPORT	25
COUNTRY	್ ಸ್ಟ್ ಕ್ಷ್		DATE DISTR. 28 Tag 1053
NUBJECT	Mark Stonpages at SMV Units Equipment Chortages	Caused by	NO OF PAGES 1
			NO OF ENCLS.
		25X1	SUPPLEMENT TO REPORT NO.
AND DOOR HIMSON D. O.	CONTAINS INFORMATION AFFECTING THE MATIONAL DIFFERSE STATES WITHIN THE MEANING OF THE SEPPONAGE ACT SO	manen es an	NEVALUATED INFORMATION
OF CES CONTENTS	ELAS AMERICUD. ITS TRANSDISSION ON THE REVELATION DIM ANY MARKET TO AR UNAUTHONIZED PERSON IS PRO- REPRODUCTION OF THIS FORM IS PROVINCED.	THE 15 01	25

- ... On 7 April 1953, work at six drill rigs of SNV Bohrbetrieb II was subreaded because of a lack of ? 3/4 inch drilling bits. One freight car conthining 350 drilling bits was despatched from the Soviet Union on 31 Carch 1753 but the shipment was not expected to arrive in Vienna for about threeweeks. The SEV has tried in vain to purchase drilling bits of the Hame dimension from Czechoslovakia, Hungary and Rumania.
- 2. The Seismographic Section of the SAV resumed work the end of March 1895 after a short stoppage due to a lack of a special type of tubes desiribed as thin iron pipes used for holding powder charges. Appearently midtubes were delivered by Rohrwalzwerk after the debt of 950,000 schillings ans paid for previous deliveries,2

25X1 25X1

Comment: Rohrwalzwerk is the Amstetten oranch of USIA-controlled Berndorfer M. tallwarenfabrik A.G.

		CLASSIFICATION	SECRET	25X1
		K NERE		
ARMY	-I AIR	2 FBI		

25X1